SHUTTLE CRITICAL ITEMS LIST - ORBITER

SUBSYSTEM : EPD&C - FWD-RCS FMEA NO 05-6KF-2111 -1 REV:11/03/

ASSEMBLY : FWD FCA 3 :RLR42C1201GM P/N RI

CRIT. FUNC: CRIT. HDW: VEHICLE 102 103

P/N VENDOR: QUANTITY 2.1 :ONE

104 EFFECTIVITY: X X X

LOXOOXDO LS PHASE(S): PL

PREPARED BY:

APPROVED BY:

REDUNDANCY SCREEN: A-PASS B-FAIL C-PA APPROVED BY (NASA):

DES ŘEL QE

D SOVEREIGN J BEEKMAN

DES SSH SSH MERROW CLASS 11-21-87 RELATERATED LOS 104.50 REL QΕ

WYTH OF RE

EDDAR SOME KELLED THE SOMETHING

FOR we of Grance

ITEM:

CURRENT LIMIT RESISTOR (1.2 KILO CHM, 2 WATT) - FORWARD RCS REACTION JE DRIVER 2 (MANIFOLD L5/F5/R5 POWER CIRCUIT) - STIMULUS TO REMOTE POWER CONTROLLER 37.

FUNCTION:

CONDUCTS CIRCUIT CURRENT AND PROVIDES CURRENT LIMITING FOR A STIMULUS INPUT TO REMOTE POWER CONTROLLER (RPC) 37 FROM THE REACTION JET DRIVER FORWARD (RJDF) 2 VERNIER JET CONTROL (MANIFOLD L5/F5/R5) POWER CIRCUIT. 83V76A24A1R89.

FAILURE MODE:

OPEN, ELEMENT OPENS.

CAUSE(S):

STRUCTURAL FAILURE, VIERATION, MECHANICAL SHOCK

EFFECT(S) ON:

- (A) SUBSYSTEM (B) INTERFACES (C) MISSION (D) CREW/VEHICLE
- (A) LOSS OF REDUNDANCY.
- (B) NO EFFECT FIRST FAILURE.
- (C,D) NO EFFECT.
- (E) FUNCTIONAL CRITICALITY EFFECT PRIMARY USE IS FOR VERNIER THRUSTER OPERATION. IN ADDITION PROVIDES REDUNDANCY FOR PRIMARY THRUSTER USE. POSSIBLE LOSS OF CREW/VEHICLE DUE TO LOSS OF CAPABILITY TO PERFORM EXTERNAL TANK SEPARATION AFTER LOSS OF ALL REACTION JET DRIVER POWER. REQUIRES 3 OTHER FAILURES (DRIVER RPC DIODE OPEN, TWO THRUSTERS FAIL OF BEFORE THE EFFECT IS MANIFESTED. FIRST FAILURE OF STRING NOT DETECTABL IN FLIGHT DUE TO LACK OF MONITORING MEASUREMENTS.

SHUTTLE CRITICAL ITEMS LIST - ORBITER

SUBSYSTEM : EPD&C - FWD-RCS

FMEA NO 05-6KF-2111 -1

REV:11/03/87

DISPOSITION & RATIONALE:

- (A) DESIGN (B) TEST (C) INSPECTION (D) FAILURE HISTORY (E) OPERATIONAL USE
- (A-D) FOR DISPOSITION AND RATIONALE REFER TO APPENDIX E, ITEM NO. 1 \sim RESISTOR, FILM.
- (B) GROUND TURNAROUND TEST

COMPONENT CHECKED OUT EVERY FLIGHT DURING GROUND TURNAROUND VIA THE GUIDANCE, NAVIGATION, AND CONTROL (GN&C) ORBITER MAINTENANCE REQUIREMENTS AND SPECIFICATIONS DOCUMENT (OMRSD) REQUIREMENTS FOR CHECKING THE PRIMARY AND VERNIER REACTION JET DRIVER POWER. THE TESTING CONSISTS OF CYCLING THRUSTER REACTION JET DRIVER LOGIC AND DRIVER SWITCHES WHILE MONITORING VEHICLE INSTRUMENTATION TO DETERMINE IF COMPONENTS HAVE FAILED.

(E) OPERATIONAL USE NO ACTION FOR FIRST FAILURE - NOT DETECTABLE.